Auditors Complex, Annex Building 2 Corners of Independence Avenue, 15th Street SW and 14th Street SW Washington District of Columbia HABS No. DC-524-B

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

rm 10-920 une 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS DL, WASH, 395B

ARCHITECTURAL DATA FORM

	·	· · · · · · · · · · · · · · · · · · ·		
TATE	COUNTY		TOWN OR VICINITY	
District of Columbia			Washington	
HISTORIC NAME OF STRUCTURE (INCL	UDE SOURCE FOR	NAME)		HABS NO.
Auditors Complex, Annex Building 2				DC-524 -B
SECONDARY OR COMMON NAMES OF STRUCTURE				
South Outbuilding and Old Laundry				
OMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)				
Corners of Independence Avenue, 15th Street SW and 14th Street SW, Washington, D.C.				
DATE OF CONSTRUCTION (INCLUDE SOURCE)		ARCHITECT(S) (INCLUDE SOURCE)		
1902 (Source: Sprague)		James Knox Taylor (Source: Sprague)		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The work of the currency printing and Engraving), Annex 2 was built as a laundry for the cleaning of rag goods required for the high-quality currency printing that cook place in the Main Auditors Building. By 1920, the building also was used to store (contd) of the Leiner of the Main Auditors Building. By 1920, the building also was used to store (contd) of the APPROPRIATE) Commercial/utilitarian style, with exterior decorative elements of elemish, vernacular styled end gables and dormers. AATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Granite base and brick masonry walls. The property of the Main Auditors are wooden and window mings are segmented by brick arches. AAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) ong, narrow two story building with gabled roof and eaves with projecting shaped rafterends. EXTERIOR FEATURES OF NOTE The property of the four architects of the four plans under HABS No. DC-524 EXTERIOR FEATURES OF NOTE The property of the four architects of the four plans under HABS No. DC-524 EXTERIOR FEATURES OF NOTE The property of the four architects of the four plans under the four architects of				
NTERIOR FEATURES OF NOTE (OESCRIBE FLOOR PLANS, IF NOT SKETCHED)				
Interior brick surfaces left plain or painted, exposed steel roof trusses, paneled wood wainscotting and ceiling in north ground floor room. See floor plans under HABS No. DC-524 AUDITORS COMPLEX, ANNEX BUILDINGS				
MAJOR ALTERATIONS AND ADDITION only minimal changes in the formortion that presently is occupant.	rm of window and		-	1
RESENT CONDITION AND USE Present structural condition generally is good, but west-end has een vacant for more than a decade and suffers from cumulative lack of maintenance. Building artially occupied by GSA and Holocaust Memorial Council file cabinets.				
THER INFORMATION AS APPROPRIATION is concrete and wall a xis and spans between 14th and	and ceiling fin	ish, exposed maso	nry. Building	lies on east-west

lose proximity to its flanking buildings, namely Main Auditors and Annex 1.

OURCES OF INFORMATION (INCLUOING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)

isted on National Register. See bibliography and also Paul Sprague's "Historic Structures eport" for more complete information and photographs (report in possession of GSA Region 3) se HABS No. DC-524 AUDITORS COMPLEX, ANNEX BUILDINGS and HABS No. DC-524-A AUDITORS (cont'd)

OMPILER, AFFILIATION
nna R. Cohn, U.S. Holocaust Memorial Council

DATE

May 2, 1985

ARCHITECTURAL DATA FORM- CONTINUATION SHEET

Significance: printing equipment. By 1950, however, Annex 2 was used exclusively for GSA storage.

Sources of Information: COMPLEX, ANNEX BUILDINGS 1 AND 1/A for more information on the complex.